



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

September 05, 2007

Supervisor DR7

Mine Name: Western Clay Company
Operator Name: Redmond Limestone Quarry.

Permit number: M/041/004
Inspection Date: August 27, 2007
Time: 2:30 pm

Inspector(s): Lynn Kunzler, DOGM
Other Participants: none
Mine Status: Active

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation
10. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

There was no activity at this site during this inspection, however the site is considered active. There has not been any apparent activity for several weeks at this site. While the screen was still on site, there was no other equipment noted.

There were no erosion problems, litter, or deleterious materials noted on site.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor this site when in the area.

Inspector's Signature

LK:pb

O:\M041-Sevier\M0410004-Redmond Limestone Quarry\Inspections\Insp-08272007.doc